

Site Inspection Photos – Pymble Ladies College (PLC)

- A. View of oval and drop off/pick up near Reception
- B. View looking south from within Junior School
- C. Existing Dance Studio located within Junior School
- D. View looking south-east towards the Project area and rear of Goodlet House
- E. View looking south-west towards Mollie Dive Field
- F. View of Aquatic and Fitness Centre
- G. View within Centenary Car Park
- H. View of Jeanette Buckham Gymnasium (JBG) entry
- I. View looking east towards the Project area from JBG entry
- J. View looking north-east towards the Project area from JBG entry
- K. View from Project area looking south-east
- L. View from Project area looking north-west towards Goodlet House
- M. View from Project area looking south towards adjoining property at 59B Pymble Avenue
- N. View from Project area looking south-east towards adjoining property at 57A Pymble Avenue
- O. Entry to Grey House Walk (GHW) from access gate on campus
- P. View along GHW looking south-east towards Pymble Avenue
- Q. View from Project area looking north-east
- R. View from Project area looking north towards Junior School
- S. View of service access path located along the southern boundary
- T. View of area rear of sporting courts from service access path
- U. View of external area of Centenary Car Park
- V. View along GHW looking north-east towards PLC

SITE INSPECTION PHOTOS

30 August 2022

A.



B.



C.



D.



E.



F.



SITE INSPECTION PHOTOS

30 August 2022

G.



H.



I.



J.



K.



L.





SITE INSPECTION PHOTOS

30 August 2022

M.




N.



O.



P.



Q.



R.



SITE INSPECTION PHOTOS

30 August 2022

S.



T.



U.



V.

